



## Notice of Retirement: Communication Server 1000 (CS1K) Release 3.0 Software

### Notice:

This bulletin replaces bulletin 2007008131.2. This update has been issued to communicate some new information regarding the issue.

**BULLETIN ID:** 2007008131, Rev 3  
**PUBLISHED:** 2008-06-25  
**STATUS:** Active  
**REGION:** APAC  
CALA  
EMEA  
GC  
NA  
**PRIORITY:** Major  
**TYPE:** Bulletin

### Reissue Reason:

Revision 2 of this bulletin moved the MD date from July 2 to Aug 4, 2008. At that time, the Last Time Order date was not set correctly. This bulletin sets the last time order date to July 25, 2008 for the receipt of clean orders. This is the standard lead time for order to be received and scheduled before the final MD date.

### Background:

In preparation for the new life cycle management (LCM) policy being issued later this month, this bulletin is to provide advance notification for Retirement/MD status for Communication Server 1000 Release 3.0 Software (formally known as Succession Release 3.0).

### Analysis:

Succession 3.0 Software has been available for New Systems Sales and Upgrades since October 27, 2003. This Bulletin serves as official Global notification of Manufacture Discontinue / Retirement status for all Regions for the purpose of Software Life Cycle Management.

X21 Release 3.0 (including DSN version) is planned for Retirement Globally as of Aug 4, 2008; and planned for End of Life status as of July 2nd, 2010.

Orders must be received by Nortel, in ready to order status no later than July 25, in order to be scheduled before the Aug 4, 2008 MD deadline.

Customer notification of the decision to retire/MD the product noted above:

Last Ship Date:	August 15, 2008
Last Time Order Date:	July 25, 2008
Manufacture Discontinue (MD) / Retirement Date:	August 4, 2008
End of Life (EOL) Date:	July 2, 2010
Last Supported Software Release:	03.00
Market Regions Affected:	Global

### Recommendations:

Alternative/Replacement Products/Solutions

The Current X21 software release is considered to be the replacement product. At this time, X21 Release 5.5 is Current and at General Availability status.

Refer to X21 Release 5.0 Product Bulletin: P-2007-0179-Global on upgrade strategy.

Refer to the Enterprise Solutions Life Cycle Management Policy for definitions for MD/Retirement status support.

### Required Actions:

It is recommended to contact your Nortel representative to assist in upgrade planning.

### Attachments:

There are no attachments for this bulletin

### Footer Information:

### Retirement Reason:

Per LCM policy

### For Additional Information:

- Product Bulletin P-2004-0072-NA Succession Enterprise 3.0 Software
- Product Bulletin P-2006-0005-Global: Meridian 1 / Communication Server 1000 Life Cycle Management Status

### Products and Releases:

The information in this bulletin is intended to be used with the following products and associated releases:

PRODUCT	RELEASE
Enterprise VoIP-Core-CS 1000M Chassis/Cabinet	03.00
Enterprise VoIP-Core-CS 1000M Half Group	03.00
Enterprise VoIP-Core-CS 1000M Multi Group	03.00
Enterprise VoIP-Core-CS 1000M Single Group	03.00
Enterprise VoIP-Core-CS 1000S	03.00
Enterprise VoIP-Core-MG 1000B	03.00

To view the most recent version of this bulletin, access technical documentation, search our knowledge base, or to contact a Technical Support Representative, please visit Nortel Technical Support on the web at: <http://support.nortel.com/>. You may also sign up to receive automatic email alerts when new bulletins are published.

**REFERENCE:**  
**PRE-REQUIRED PATCH:**  
**PATCH ID:**

Copyright 2007 Nortel Networks. All rights reserved. Information in this document is subject to change without notice. Nortel assumes no responsibility for any errors that may appear in this document. The information in this document is proprietary to Nortel Networks.

Nortel recommends any maintenance activities, such as those outlined in this bulletin, be completed during a local maintenance window.

Nortel, the Nortel logo, and the Globemark design are trademarks of Nortel Networks. All other trademarks are the property of their respective owners.